



Vehicle History Report



2022-08-01

ŠKODA Fabia

Located in: **Netherlands**

Vehicle reference:

TMBJM6NJ3HZ057958

Body type: **Estate**

Color: **blue**

Engine size: **1197 cm3**



Damage



Mileage Inconsistency



Number of odometer readings: 3



Number of inspection records: 1



Number of service records: 3



Quick Check

Stolen

Not reported stolen

✔ No issues reported

Mileage judgement

Consecutive odometer readings of this vehicle recorded in NAP register are always higher than previously reported mileages. RDW judges the odometer of this vehicles as logically explainable.

✔ Logical

Structural Damage

No structural damage reported to CARFAX.

✔ No issues reported

Inspections

No issues reported, no inspection due in the next 6 months

✔ No issues reported

Recalls

There are currently no recalls reported to CARFAX.

✔ No issues reported

Import

Not a private import

✔ No issues reported

Taxi

Not used as taxi

✔ No issues reported



Damage

Damage reported

❗ Damage

A CARFAX Vehicle History Report is based only on information supplied to CARFAX. Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision

about your next used car.

Highlights						
<p>Users in Netherlands</p>  <p>Number of users: 1</p> <p>Non-private users: 1</p>	<p>Vehicle age</p> <table border="1"> <tr> <td>years</td> <td>months</td> </tr> <tr> <td>5</td> <td>8</td> </tr> </table> <p>First registration date: 2016-11-04</p>	years	months	5	8	<p>Inspections</p>  <p>Latest inspection: 2020-09-16</p>
years	months					
5	8					

History information		
Date	Mileage	Event
2016-11-04		Registered in Netherlands New owner reported Commercial usage reported in Netherlands
2020-05-01	66,805 km	Maintenance performed <ul style="list-style-type: none"> ■ Spark plug replacement ■ Windshield wiper replacement Damage repaired <ul style="list-style-type: none"> ■ Bodywork paint finish
2020-05-13	66,805 km	Workshop visited
2020-07-17	12 km	Workshop visited
2020-09-16		Inspected in Netherlands Inspection passed
2021-12-21		New owner reported For sale usage reported in Netherlands
2021-12-29		New owner reported For sale usage reported in Netherlands
2022-01-03		New owner reported Owner type: dealer For sale usage reported in Netherlands
2022-01-15		New owner reported For sale usage reported in Netherlands
2022-04-29		New owner reported For sale usage reported in Netherlands
2022-05-20		New owner reported For sale usage reported in Netherlands

Date	Mileage	Event
2022-06-02		Vehicle insured

Based on data reviewed from 22 countries in Europe and North America

CARFAX Glossary

Damage

Damage can be a result of many different types of events. Examples include contact with objects (other vehicles, trees, traffic signs, road debris, etc), vandalism, fire, flood, or other weather-related events. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Mileage Inconsistency

This indicates that there is a more recent odometer reading that has less mileage than an older reading. This discrepancy could be the result of a rollback or a clerical error. You should verify the mileage with a qualified mechanic

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Service records

CARFAX has an extensive database of service records, including oil changes and other routine maintenance procedures. Remember to also ask the seller for service and maintenance records.

Users

Total number of users in a given country, registered both for private and non-private use.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.